Oil Field Environmental Incident Summary

Date/Time of Notice: 03/14/2014 07:39 Incident: 20140314073940 Responsible Party: XTO ENERGY INC. Well Operator: XTO ENERGY INC. Well Name: LINDVIG 32-9 Field Name: CAMP Well File #: 14820 Date Incident: 3/13/2014 Time Incident: 12:50 Facility ID Number: **MCKENZIE** Twp: 152 **Rna:** 101 **Sec:** 9 County: Location Description: Submitted By: Scot Richardson Received By: Contact Person: Scot Richardson P.O Box 6506 Williston, ND 58801 General Land Use: Well/Facility Site Affected Medium: Well/Facility Soil **Distance Nearest Occupied Building:** Distance Nearest Water Well: Type of Incident: Stuffing Box Leak Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: No Spilled Units Recovered Units Followup **Units** 2 Barrels Oil **Brine** Other **Description of Other Released Contaminant:** Inspected: Written Report Received: Clean Up Concluded: Risk Evaluation: NONE Areal Extent:

Potential Environmental Impacts:

NONE

Action Taken or Planned:

The spill was contained on location. The flow line was cleaned and the well head stuffing box packing was replaced. Cleanup crew will collected free liquids and return to production tank. Soil remediation will be done and impacted soil will be collected and hauled to an approved disposal facility.

Wastes Disposal Location: Indian Hills Disposal

Agencies Involved:

Updates

Date: 3/17/2014 Status: Reviewed - Assigned to Other Agency Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.